


# 鐵 - 碳平衡圖 Fe - C Equilibrium Phase Diagram



A<sub>2</sub>: Magnetic point  
鐵的磁性變態點

A<sub>0</sub>: Magnetic change of Fe<sub>3</sub>C  
雪明碳體的磁性變態點

— Fe - Fe<sub>3</sub>C Equilibrium diagram Fe - Fe<sub>3</sub>C 平衡圖

- - - Solubility of graphite in liquid Fe 液相鐵中石墨溶解度

- · - · - Cementite liquidus (calculated) 液相鐵中Fe<sub>3</sub>C溶解度 (計算值)